

DARDEN ARCHITECTS
April 11, 2019

PROJECT: 1843 RC Performing Arts Center

Facilities Meeting Notes

Attendance:

Martin Ilic, Darden Architects

William Brandle, Darden Architects

Jim Rooney, Director of Maintenance and Operations

Michael Kaiser, RC Building Services

Notes:

High parapet walls should be provided in the areas of rooftop mechanical equipment for the safety of servicing personnel.

Stage electrical needs an oversized door for servicing and future replacement of equipment.

Design of lighting in the art gallery needs to allow for flexibility.

Include a wall toe kick in the art gallery walls to allow for easier painting.

Fire pump enclosure should be examined to make susign teery 0(ex6m)2()JT(D4Tyr9)de cñM02n7s afButArt

